



DEPARTMENT OF THE ARMY

NEW ENGLAND DIVISION, CORPS OF ENGINEERS

424 TRAPELO ROAD

WALTHAM, MASSACHUSETTS 02154

20 September 1971

Mr. William Burpee Room 2344 Rayburn Building Washington, D. C. 20515

Dear Mr. Burpee:

These are photographs portraying typical erosion at Gay Head Cliffs as requested by you by telephone to Colonel Mason and in subsequent conversation with me. To expedite, we are forwarding them informally.

Sincerely yours,

CECIL E. WENTWORTH Chief, Beach Erosion Unit

Incl
As stated

d J. A. F.

262 W SXID " DON'ELL SAME MA What this uneyme I we am 15+ Spirial Operations Wing


700 271 60°W HO221001 N 70027100W 41022'00 N 5.3.2 5.3.1

Digitized by the Internet Archive in 2012 with funding from Federally funded with LSTA funds through the Massachusetts Board of Library Commissioners


http://www.archive.org/details/hastingskeithpap28keit
















Shiri shir with a price and in its 5.3.9 Gay Lear Cuys with Sharling 70043152" w 41020,25N 70043, 45-W Whichas VIII alma crois on since, isoy Gay Head Ough carin Shouldwee 41 021,00x1 70 046/30" W Bay week Webbs we in Showelent 41019145"> Mosts 30" W 5.3.10 Gay Had Wife with Shoreling 41021100X1 76040130W 5.3,8 marked visiguel Shoullenin



















41022146"X 40045100" w Wie the Vendland of allen Der as 1800 4,022,40"x1 70045100" W murhus Vinguest Shallows 41027'00'14 70040'00"W 6.3.18 murdus venguell Sharlessi 5.3.17 mer than Uniquet Shallers 41021130 M 76027180"W markad unyout Sharehard mai that Unyand Samiland 41027100N 70040100110 410 21, 30hl 76027100 W 5.3.13 markus Venyund Thurling 5.3.14 marchas Vinywal Shwelens 766 10 8×10











5.3.27.8 have - Sharp religio, ramino and 5,3,28.9 hamme were ection remones fines down wach makered punch by winds. Mario, and Sieven asker Buristo, in of like of Mills

5.3.26. 7 Consumer Degree Class in Calify, 25 g 5.3.24's Vest slumping 1967 or with continued 5.3. 22 3. Obree- up- upper slope - Fin pouls regular 5.3. 23 4. small verment view 1967 - nd chap. 3. 23. 43. 4. small response of the servented. 5. 3. 25. 6 Continuent Deposit of Some Dechors 5.3.21 2. Moreil stud - Winnity of old Cook Flowed Staron, 1967. how has been biglly mond woon ly Mainthe William of Waring a old 5. 3. 20 Lage well mond desired found Siger Aprilable ittilland tilling



1. Large circular slide at top of cliff, 1967. Now has moved partially down slope.


.

.

*,







Close up - upper slope - fine sands rapidly eroded by wind, rain and storm water runoff, 1967.


N. I. A. A.



since seriously deteriorated.

X - 11 ho

	Oem	الم الما	775	NEED
				1.0
				end no est of a
La	5.1,3	יוכסק	1	room of the same
	M	KA	4	451 BA4



5. 3. 24.5

(x5./3700%)



Continuous seeping from interior springs cause rapid loss of some sectors of cliffs, 1967.

1/2 /L. 1 h




Note - sharp ridges, ravines and down-wash material caused by winds, rains and storm water runoff, 1967.



9. Normal wave action removes fines at base of cliffs.

18.2-12. Los 61 18.02. V. Los VIII.



Continuous seeping from interior springs cause rapid loss of some sectors of cliffs, 1967.

